



DS-9000/DS-2600 Firmware Release Ver.1.030

1. New Firmware Version

Firmware 1.03 fixes bug that causes a "noise" that may occur during playback of a recorded file.

2. Phenomenon:

When you playback throughout the file, noise will occur from the part that is damaged and will continue to the end of the file. If you stop playback slightly after the point at which the noise occurred and resume playback, file will playback correctly from that point onwards.

3. Cause of the failure

Depending on the timing when you stop the recording, wrong information may be written to the header of the file.

4. Corrective Action:

Corrected the way the recorder writes information to the file header.

5. Contents of release:

- Win version updater for DS-9000 and DS-2600.
- Mac version updater for DS-9000 and DS-2600.
- Uploading the DS-9000 binary file to the download server.

*The SCP does not support the DS-2600, so there is no binary file.

6. Download site:

Dealer Support Center

<https://proportal.olympusamerica.com/type/firmware-ds-series-9000/>

EOD