

DS-9000/DS-2600 Firmware Release Ver.1.070**1. New Firmware Version**

F/W: Ver1.070 (The version will be displayed as Version 1.07 for customers.)

2. Content


Fix Firmware issue.

3. About the contents of the firmware issue fixes.

- 1) Fixed the issue that the playback does not start at the point where it stopped before. (DS-9000 and DS-2600.)
- 2) Fixed the issue that not all Worktypes are being shown, if 9 or more Worktypes and 2 or more Authors are registered on the device. (DS-9000)

4. Phenomenon , Cause of the failure and Measures

- 1) Currently during the playback process, remaining part of a segment is being skipped when the playback stops. Therefore, when you playback again, milliseconds are skipped.



- 2) Maximum number of Worktypes that can be shown on the device had been the same as the number of Authors on the device. This bug will be fixed with this release.

EOD